

# Manhole Inspection Summary

Manhole # S15C\_\_064MH

Printed On: 8/6/2009

Page 1 of 3

**Inspection** ☒ **Is Incomplete** Rating: **3) Fair**

Record Plat: **15C** Node: **064** Status: **Found**

Insp Date: **6/15/09 9:40 AM**

Incomplete Comments

**Cannot Access – Relatively New Manhole With Internal Aluminum Grate Platform Blocking Access.**

Crew: **ADS2**  
Inspector: **ADS2**  
Firm: **ADS**

**Location** Address: **EVERGREEN ST** Cross Street: **W. FRANKLIN ST**

**Manhole** Type: **Siphon** Location: **Roadway** Ground Conditions:  
☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **None**

Comments **STEEL GRADE COVERING THE ENTIRE BOTTOM OF THE MANHOLE**

**Cover** Shape: **Circular** Diameter: **32** (in.) Length: (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

**Frame** Offset: **0** (in.) Condition: ☒ Sound ☐ Cracked ☐ Leaks

**Chimney / Frame Adjustment** ☒ Exists Material: **Brick and Concrete** ☐ Parged Height: **22** (in.)

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Corbel** Material: **Concrete** ☐ Parged Type: **Flat top**

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Barrel** Material: **Unknown** ☐ Parged

Shape: **Rectangular** Diameter: **81** (in.) Length: **91** (in.)

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Bench** ☐ Exists Material: ☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Channel** Material: **Unknown** ☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Steps** Count: **7** Missing: **0** ☐ Corroded

**Surcharge** ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

# Manhole Inspection Summary

Manhole # S15C\_\_064MH

Printed On: 8/6/2009

Page 2 of 3

Location View



Top View



Top View



